



## Inspection Detail



<b>Client:</b>	HDD Broker		
<b>Inspected by:</b>			
<b>Location of Inspection:</b>			
<b>Phone No / Email:</b>			
<b>Date of Inspection:</b>	6/15/2026	<b>Job#:</b>	
<b>Year:</b>	2016	<b>Make:</b>	Vermeer
<b>Model:</b>	D24X40III	<b>VIN/SN:</b>	

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Inspection Details

### Unit Information

<b>Hours:</b>	3,895	<b>Date:</b>	N/A
---------------	-------	--------------	-----

### General Body

<b>Paint condition:</b>	See Notes	<b>Panel dents:</b>	No	<b>Corrosion:</b>	No
<b>Dents/Bends:</b>	Yes	<b>Visible leaks:</b>	Yes	<b>Operator console pivot/lock:</b>	No Damages Observed
<b>Operator's Seat:</b>	See Notes	<b>Operator Console Joysticks, switches, gauges:</b>	See Notes	<b>Fresh water tank (if applicable):</b>	N/A

### Safety Equipment

<b>Operator's presence switch (seat):</b>	No Damages Observed	<b>Safety switches:</b>	No Damages Observed	<b>Red safety bars (rod loader extensions):</b>	No Damages Observed
<b>Work lights:</b>	No Damages Observed	<b>Strike alert/ground wire:</b>	No Damages Observed	<b>Safety decals:</b>	No Damages Observed

### Breakout System

<b>Breakout jaw wear:</b>	No Damages Observed	<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins/bushings slop:</b>	No Damages Observed
<b>Front Stakedown System:</b>	No Damages Observed	<b>Auger condition:</b>	No Damages Observed		

### Main Drive System

<b>Tracks (steel or rubber):</b>	Steel	<b>Track condition:</b>	See Notes	<b>Sprockets/rollers:</b>	No Damages Observed
----------------------------------	-------	-------------------------	-----------	---------------------------	---------------------

### Rear Outriggers

<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins and bushings:</b>	No Damages Observed	<b>Bent/broken parts:</b>	No
-------------------------------------	---------------------	---------------------------	---------------------	---------------------------	----

### Carriage

<b>Wear pads/carriage slop:</b>	No Damages Observed	<b>Motors and hoses condition:</b>	No Damages Observed	<b>Rack and pinion condition:</b>	No Damages Observed
---------------------------------	---------------------	------------------------------------	---------------------	-----------------------------------	---------------------

### Engine Details

<b>Fluid level and condition:</b>	No Damages Observed	<b>Visible leaks:</b>	No	<b>Belts and pulleys:</b>	No Damages Observed
<b>Engine mounts:</b>	No Damages Observed	<b>Radiator/hoses:</b>	No Damages Observed		

### Operation

<b>Engine start and idle:</b>	Yes	<b>Engine smoke:</b>	No	<b>Engine noises (tick/knock):</b>	No
<b>Rear outrigger operation:</b>	No Damages Observed	<b>Main rack tilt:</b>	No Damages Observed	<b>Front stakedown rotation/up/down:</b>	No Damages Observed
<b>Breakout vices open/close/rotate:</b>	No Damages Observed	<b>Rod loader lift/shuttle/alignment:</b>	No Damages Observed	<b>Carriage traverse (thrust/pullback):</b>	No Damages Observed
<b>Rotation motor fwd/reverse:</b>	No Damages Observed	<b>Mud pump on/off:</b>	No Damages Observed		

### Drill Rods

<b>Rod count:</b>	50	<b>Bent rods:</b>	No	<b>Thread condition:</b>	No Damages Observed
<b>Corrosion:</b>	No				

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Tracks

<b>Left Track Condition:</b>	See Notes	<b>Left Track Brand:</b>	Obstructed	<b>Left Track Size:</b>	Obstructed
<b>Left Track Tread Depth Measurement:</b>	N/A"	<b>Left Track Rollers:</b>	No Damages Observed		
<b>Right Track Condition:</b>	See Notes	<b>Right Track Brand:</b>	Obstructed	<b>Right Track Size:</b>	Obstructed
<b>Right Track Tread Depth Measurement:</b>	N/A"	<b>Right Track Rollers:</b>	No Damages Observed		

## Observations / Comments

The unit starts and operates.
-------------------------------

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Wear and Tear Items

Item Name	Item Comments
Left Track	The track rubber is completely damaged, exposing its iron pads.
Right Track	The track rubber is completely damaged, exposing its iron pads.
Heat Shield	The heat shield inside the engine compartment is damaged.
Tilt Cylinder	The tilt cylinder seal of the rod compartment is deformed.
Leak	Underneath the vice, a leak is visible.
Front Stabilizer Rod	The right stabilizer rod has minor dents.
Rust	The unit body has multiple areas of rust over the paint.
Hydraulic Hose Insulation	Some hydraulic hose covers near the vice are damaged.
Hydraulic Lines	Some hydraulic lines and connections show rust.
Greaser	The greaser system above the bucket is wet, which may be leaking.
Wire Insulation	A wire insulation near the exhaust muffler is damaged.
Door Latch	The latch of the storage compartment near the rear controls is missing, leaving its door loose.
Seat	The seat cover on the bottom appears to be torn.
Joystick Switches	All switch covers are faded and slightly worn.
Hydraulic Oil Level	The hydraulic reservoir level is low.
Paint	The paint has scratches and flaws.

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.