



Inspection Detail



Client:	HDD Broker		
Inspected by:			
Location of Inspection:			
Phone No / Email:			
Date of Inspection:	6/15/2026	Job#:	
Year:	2016	Make:	Vermeer
Model:	D23X30III	VIN/SN:	

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details

Unit Information

Hours:	3,541	Date:	N/A
---------------	-------	--------------	-----

General Body

Paint condition:	See Notes	Panel dents:	Yes	Corrosion:	No
Dents/Bends:	Yes	Visible leaks:	No	Operator console pivot/lock:	No Damages Observed
Operator's Seat:	See Notes	Operator Console Joysticks, switches, gauges:	No Damages Observed	Fresh water tank (if applicable):	N/A

Safety Equipment

Operator's presence switch (seat):	No Damages Observed	Safety switches:	No Damages Observed	Red safety bars (rod loader extensions):	No Damages Observed
Work lights:	No Damages Observed	Strike alert/ground wire:	No Damages Observed	Safety decals:	No Damages Observed

Breakout System

Breakout jaw wear:	No Damages Observed	Cylinder and hose condition:	No Damages Observed	Pins/bushings slop:	No Damages Observed
Front Stakedown System:	See Notes	Auger condition:	No Damages Observed		

Main Drive System

Tracks (steel or rubber):	Rubber	Track condition:	See Notes	Sprockets/rollers:	No Damages Observed
----------------------------------	--------	-------------------------	-----------	---------------------------	---------------------

Rear Outriggers

Cylinder and hose condition:	No Damages Observed	Pins and bushings:	No Damages Observed	Bent/broken parts:	No
-------------------------------------	---------------------	---------------------------	---------------------	---------------------------	----

Carriage

Wear pads/carriage slop:	No Damages Observed	Motors and hoses condition:	No Damages Observed	Rack and pinion condition:	No Damages Observed
---------------------------------	---------------------	------------------------------------	---------------------	-----------------------------------	---------------------

Engine Details

Fluid level and condition:	No Damages Observed	Visible leaks:	No	Belts and pulleys:	No Damages Observed
Engine mounts:	No Damages Observed	Radiator/hoses:	No Damages Observed		

Operation

Engine start and idle:	Yes	Engine smoke:	No	Engine noises (tick/knock):	No
Rear outrigger operation:	No Damages Observed	Main rack tilt:	No Damages Observed	Front stakedown rotation/up/down:	No Damages Observed
Breakout vices open/close/rotate:	No Damages Observed	Rod loader lift/shuttle/alignment:	No Damages Observed	Carriage traverse (thrust/pullback):	No Damages Observed
Rotation motor fwd/reverse:	No Damages Observed	Mud pump on/off:	No Damages Observed		

Drill Rods

Rod count:	40	Bent rods:	No	Thread condition:	No Damages Observed
Corrosion:	No				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tracks

Left Track Condition:	See Notes	Left Track Brand:	Obstructed	Left Track Size:	Obstructed
Left Track Tread Depth Measurement:	22/32"	Left Track Rollers:	No Damages Observed		
Right Track Condition:	See Notes	Right Track Brand:	Obstructed	Right Track Size:	Obstructed
Right Track Tread Depth Measurement:	18/32"	Right Track Rollers:	No Damages Observed		

Observations / Comments

The unit starts and operates.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Wear and Tear Items

Item Name	Item Comments
Lift Cylinder Chrome	The cylinder chrome from the right stake rod is scratched.
Engine Leak	Behind the engine filler cap, a hose is wet and requires closer inspection.
Turbo Hose Cover	The hose cover is torn.
Front Stabilizer Rod	The left stabilizer rod appears slightly bent.
Warning Light	A warning light is displayed on the screen and requires further diagnosis.
Left Track	The track shows minor cracks and gouges.
Right Track	The track has scratches and minor gouges.
Coolant	No coolant level was observed through the sight glass.
Dents	The unit shows minor dents on the rod storage frame.
Seat	The seat cover is slightly worn and faded.
Metal Panel	The metal panel on the right side near the engine compartment is scratched.
Fuel Tank	The fuel tank appears damaged or deformed.
Compartment Door	The engine compartment door has minor dents and is misaligned with the molding.
Paint	The unit paint has multiple flaws, scratches and minor rust forming.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.