



## Inspection Detail



<b>Client:</b>	HDD Broker		
<b>Inspected by:</b>			
<b>Location of Inspection:</b>			
<b>Phone No / Email:</b>			
<b>Date of Inspection:</b>	6/15/2026	<b>Job#:</b>	
<b>Year:</b>	2020	<b>Make:</b>	Vermeer
<b>Model:</b>	D23X30DRS3	<b>VIN/SN:</b>	

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Inspection Details

### Unit Information

<b>Hours:</b>	3,892	<b>Date:</b>	N/A
---------------	-------	--------------	-----

### General Body

<b>Paint condition:</b>	See Notes	<b>Panel dents:</b>	Yes	<b>Corrosion:</b>	No
<b>Dents/Bends:</b>	Yes	<b>Visible leaks:</b>	No	<b>Operator console pivot/lock:</b>	No Damages Observed
<b>Operator's Seat:</b>	See Notes	<b>Operator Console Joysticks, switches, gauges:</b>	No Damages Observed	<b>Fresh water tank (if applicable):</b>	N/A

### Safety Equipment

<b>Operator's presence switch (seat):</b>	No Damages Observed	<b>Safety switches:</b>	No Damages Observed	<b>Red safety bars (rod loader extensions):</b>	No Damages Observed
<b>Work lights:</b>	No Damages Observed	<b>Strike alert/ground wire:</b>	No Damages Observed	<b>Safety decals:</b>	See Notes

### Breakout System

<b>Breakout jaw wear:</b>	No Damages Observed	<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins/bushings slop:</b>	No Damages Observed
<b>Front Stakedown System:</b>	No Damages Observed	<b>Auger condition:</b>	No Damages Observed		

### Main Drive System

<b>Tracks (steel or rubber):</b>	Rubber	<b>Track condition:</b>	See Notes	<b>Sprockets/rollers:</b>	See Notes
----------------------------------	--------	-------------------------	-----------	---------------------------	-----------

### Rear Outriggers

<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins and bushings:</b>	No Damages Observed	<b>Bent/broken parts:</b>	No
-------------------------------------	---------------------	---------------------------	---------------------	---------------------------	----

### Carriage

<b>Wear pads/carriage slop:</b>	No Damages Observed	<b>Motors and hoses condition:</b>	No Damages Observed	<b>Rack and pinion condition:</b>	No Damages Observed
---------------------------------	---------------------	------------------------------------	---------------------	-----------------------------------	---------------------

### Engine Details

<b>Fluid level and condition:</b>	No Damages Observed	<b>Visible leaks:</b>	No	<b>Belts and pulleys:</b>	No Damages Observed
<b>Engine mounts:</b>	No Damages Observed	<b>Radiator/hoses:</b>	No Damages Observed		

### Operation

<b>Engine start and idle:</b>	Yes	<b>Engine smoke:</b>	No	<b>Engine noises (tick/knock):</b>	No
<b>Rear outrigger operation:</b>	No Damages Observed	<b>Main rack tilt:</b>	No Damages Observed	<b>Front stakedown rotation/up/down:</b>	No Damages Observed
<b>Breakout vices open/close/rotate:</b>	No Damages Observed	<b>Rod loader lift/shuttle/alignment:</b>	No Damages Observed	<b>Carriage traverse (thrust/pullback):</b>	No Damages Observed
<b>Rotation motor fwd/reverse:</b>	No Damages Observed	<b>Mud pump on/off:</b>	No Damages Observed		

### Drill Rods

<b>Rod count:</b>	30	<b>Bent rods:</b>	No	<b>Thread condition:</b>	No Damages Observed
<b>Corrosion:</b>	No				

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Tracks

<b>Left Track Condition:</b>	See Notes	<b>Left Track Brand:</b>	Obstructed	<b>Left Track Size:</b>	Obstructed
<b>Left Track Tread Depth Measurement:</b>	8/32"	<b>Left Track Rollers:</b>	No Damages Observed		
<b>Right Track Condition:</b>	See Notes	<b>Right Track Brand:</b>	Obstructed	<b>Right Track Size:</b>	Obstructed
<b>Right Track Tread Depth Measurement:</b>	6/32"	<b>Right Track Rollers:</b>	No Damages Observed		

## Observations / Comments

The unit starts and operates.
-------------------------------

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Wear and Tear Items

Item Name	Item Comments
Roller Support	The left support frame of the rollers is dented.
Left Sprocket	The sprocket is worn and has minor dents.
Left Track	The track is gouged and cracked.
Right Sprocket	The sprocket is worn and has minor dents.
Right Track	The track is cracked and gouged.
Coolant	No coolant level was observed through the sight glass.
Heat Shield	The heat shield inside the engine compartment is damaged.
Dents	A metal shield near the cylinder is dented.
Tilt Cylinder	The cylinder that tilts the rod storage compartment is slightly wet.
Hydraulic Leak	An oil leak was observed below the hydraulic system and requires further diagnosis.
Ignition Cover	The cover is missing.
Decals	Some decals are damaged.
Floorboard	The operator floor is slightly dented.
Seat	The seat cover is slightly worn and faded.
Metal Panel	The metal panel on the operator's left hand is slightly dented.
Armrest	There is a small hole in the cover.
Fuel Tank	The fuel tank appears damaged or deformed.
Compartment Door	The engine compartment door has minor dents and is misaligned with the molding.
Paint	The unit paint has multiple flaws, scratches and minor rust forming.

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.